## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

21V-263

**Manufacturer Name:** Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 21V-263 /WRD-21 Recall Subject: Rear Stabilizer Bracket Bolts May Detach Owner Notification Beginning Date: MAY 17, 2021

**Owner Notification End Date: JUN 11, 2021** 



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 27, 2022	2021-4	408,271	340,578	0	2,383
2	OCT 29, 2021	2021-3	408,271	313,711	0	2,449
1	JUL 23, 2021	2021-2	408,271	210,721	0	2,599

This Document Last Updated: JAN 27, 2022

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.