

# Part 573 Safety Recall Report

## 21V-343

**Manufacturer Name :** Gulf Stream Coach, Inc.**Submission Date :** JUN 28, 2021**NHTSA Recall No. :** 21V-343**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :****Manufacturer Name :** Gulf Stream Coach, Inc.**Number of potentially involved :** 246**Address :** P. O. Box 1005  
503 S. Oakland Avenue Nappanee IN  
46550**Estimated percentage with defect :** 100 %**Company phone :** 999-999-9999**Vehicle Information :****Vehicle 1 :** 2021-2021 Gulf Stream Coach, Inc. Vista Cruiser, Vintage Cruiser, Gulf Breeze, Matrix, Streamlite, Northern Express, Envision, Geo**Vehicle Type :****Body Style :****Power Train :** NR

**Descriptive Information :** Certain 2021 model year Vista and Vintage Cruiser, Gulf Breeze, Matrix, Streamlite, Northern Express, Envision and Geo Travel Trailers manufactured by Gulf Stream Coach, Inc. ("Gulfstream") do not conform to 49 CFR Part 567 – Certification and Federal Motor Vehicle Safety Standard 110 – "Tire Selection" and Section 6. On the 246 vehicles subject to this recall, the Federal Certification Label may contain incorrect Tire size and tire pressure information. Load carrying capacity of tires remains the same. Incorrect tire tag identifies the tires as being ST205/75R14D with 2200 pounds carrying capacity at 75 PSI, the substitute tire which is the subject of this recall is a ST215/75R14D with 2200 pounds carrying capacity at 65 PSI.

Subsequent review of purchasing dates of the substitute tires were identified and the universe of potentially affected units was established.

**Production Dates :** FEB 24, 2021 - MAY 05, 2021**VIN Range 1 : Begin :** 1NL1G2011M7051437 **End :** 1NL1G312XM7053037 ☒ Not sequential

## Description of Noncompliance :

Description of the Noncompliance : Certain 2021 model year Vista and Vintage Cruisers, Gulf Breeze, Matrix, Streamlite, Northern Express, Envision and Geo Travel Trailers manufactured by Gulf Stream Coach, Inc. ("Gulfstream") do not conform to 49 CFR Part 567 – Certification and Federal Motor Vehicle Safety Standard 110 – "Tire Selection" and Section 6 and CMVSS 110 of the Canadian Motor Vehicle Safety Act. On the vehicles subject to this recall, the Federal Certification Label may contain incorrect Tire size and tire pressure information. Load carrying capacity of tires remains the same.

FMVSS 1 : 574 - Tire Identification & Recordkeeping

FMVSS 2 : NR

Description of the Safety Risk : If the original label applied is incorrect there is a potential for improper inflation- of the current tires. There is a potential risk of over inflation which could result in reduced traction and performance of the tires as well as cause uneven tire wear potentially resulting in poor handling and an increased risk of crash.

Description of the Cause : Through a product change [Tire size substitute by supplier] the information was not updated correctly resulting in incorrect tire size and tire pressure information being made available for printing the incorrect Federal Tire Tags originally installed.

Identification of Any Warning that can Occur : NR

## Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

Gulf Stream Coach became aware of the incorrect tire tag information through a quality yard audit of finished products on hand. Once identified, immediate containment of finished units on hand with incorrect tire tag information were segregated and labeled with DO NOT SHIP stickers until such time as replacement tire tags with corrected information were applied, audited and released for shipment. Subsequent review of purchasing dates of the substitute tires were identified and the universe of potentially affected units was established.

**Description of Remedy :**

Description of Remedy Program : Gulf Stream Coach, Inc. will send replacement certification labels, instructions and notification letters.

How Remedy Component Differs from Recalled Component : Incorrect tire tag identifies the tires as being ST205/75R14D with 2200 pounds carrying capacity at 75 PSI, the substitute tire which is the subject of this recall is a ST215/75R14D with 2200 pounds carrying capacity at 65 PSI.

Identify How/When Recall Condition was Corrected in Production : Replacement tire tags with correct information were created and applied

**Recall Schedule :**

Description of Recall Schedule : Upon the approval of the recall, draft notification letters will be created for approval. Once approved printing of the letters will begin then put with correct tags and mailed.

Planned Dealer Notification Date : JUN 28, 2021 - JUL 02, 2021

Planned Owner Notification Date : JUN 28, 2021 - JUL 02, 2021

\* NR - Not Reported