

U.S. Department of Transportation

National Highway Traffic Safety Administration

May 25, 2021

Ms. Zoila Turley Regulatory Compliance Manager Ducati North America 448 E. Middlefield Road Mountain View , CA 94043

Subject: Turn Signals Are Not Bright Enough/FMVSS 108

Dear Ms. Turley:

This letter serves to acknowledge Ducati North America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

DUCATI/SCRAMBLER/2021

Mfr's Report Date: May 17, 2021

NHTSA Campaign Number: 21V-361

Components:

EXTERIOR LIGHTING:TURN SIGNAL

Potential Number of Units Affected: 228

Problem Description:

Ducati North America (Ducati) is recalling certain 2021 Scrambler 800 Night Shift motorcycles. The front and rear turn signal lights may not flash brightly enough. As such, these motorcycles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence:

Turn signal lights that aren't bright enough can reduce other driver's ability to see that the turn signals have been activated, increasing the risk of a crash.

Remedy:

Dealers will replace the front and rear turn signals, free of charge. Owner notification letters are expected to be mailed June 23, 2021. Owners may contact Ducati customer service at 1-888-391-5446. Ducati's number for this recall is SRV-RCL-21-009.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Ducati's proposed owner notification letter and approved it for distribution.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-107DM

21V-361

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Ducati North America's contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

