



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 2, 2021

Mr. Craig Cox
Codes and Compliance Manager
Newmar Corporation
355 N Delaware Street
Nappanee, IN 46550

NEF-107MR
21V-372

Subject: High Pressure Fuel Rail Assembly May Leak Fuel

Dear Mr. Cox:

This letter serves to acknowledge Newmar Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NEWMAR/DUTCH STAR/2017-2022
NEWMAR/MOUNTAIN AIRE/2017-2019
NEWMAR/NEW AIRE/2021
NEWMAR/VENTANA/2019-2021

Mfr's Report Date: May 20, 2021

NHTSA Campaign Number: 21V-372

Components:

FUEL SYSTEM, DIESEL:FUEL INJECTION SYSTEM:FUEL RAIL

Potential Number of Units Affected: 1,294

Problem Description:

Newmar Corporation (Newmar) is recalling certain 2017-2022 Dutch Star, 2017-2019 Mountain Aire, 2019-2021 Ventana and 2021 New Aire motorhomes. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak.

Consequence:

A fuel leak in the presence of an ignition source increases the risk of a fire.

Remedy:

Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters are expected to be mailed July 19, 2021. Owners may contact Newmar customer service at 1-800-731-8000. Newmar's number for this recall is Cummins 21E-032.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please ensure the following requirements are met:

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Newmar Corporation's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement