

21PBD - Cummins PX9 and ISX12 Fuel Rail Leak – NHTSA ID: 21V391 / TC: 2021-323, Cummins Recall: C2423

 [Edit](#)  [Clone](#)

Number

21PBD

Supplier

Cummins

Description

Safety Recall – Cummins PX9 and ISX12 Fuel Rail Leak – NHTSA ID: 21V391 / TC: 2021-323, Cummins Recall: C2423

Date

6/22/2021

What's New

Safety Recall – Cummins Fuel Rail Leak – NHTSA ID: 21V391 / TC: 2021-323, Cummins Recall: C2423. **Updated: repair procedure is now available.** Cummins PX9 and ISX12 fuel rails may leak around a sealing washer, potentially resulting in fuel leaks. Undetected prolonged diesel fuel spray in the presence of an ignition source may increase the risk of fire. The fuel rail assembly will be inspected and, if necessary, repaired or replaced.

Introduction

Cummins Inc has decided that a defect which relates to motor vehicle safety exists in certain model 567, 520, 367, 365, 348 and 337 vehicles manufactured from 01/16/2017 through 09/15/2020 with Cummins PX9 and ISX12 engines.

Cummins PX9 and ISX12 fuel rails may leak around a sealing washer, potentially resulting in fuel leaks.

The fuel rails may have undersized pilot bores for the sealing washer, thus preventing the washer from sealing properly. Undetected prolonged diesel fuel spray in the presence of an ignition source may increase the risk of fire.

Resolution

Safety Recall

Go to Cummins QuickServe and refer to the Cummins Recall – C2423.

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. If you are not using Service Management to start repair orders, review SIR for "Complete" or "In Process" next to the "C2423" Cummins campaign code prior to performing this repair.
3. Follow the procedures in Cummins C2423 Safety Recall to inspect and, if necessary, repair or replace the fuel rail assembly.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

Go to Cummins QuickServe and refer to the Cummins Recall – C2423. File warranty claims through the Cummins warranty system.

SIR will indicate chassis involved in this recall with the designator of "C2423" in the campaign field.

Links

[Chassis List](#)

Authored by: PR

Revision History

07/23/2021 - Updated: repair procedure is now available. Added Chassis List.