



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

June 8, 2021

Mr. Mick Friedt  
REV Recreation Group  
1010 Commerce Drive  
Decatur, IN 46733

NEF-107MR  
21V-395

**Subject:** Floor Structure May Be Improperly Sealed

Dear Mr. Friedt:

This letter serves to acknowledge REV Recreation Group's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

FLEETWOOD/BOUNDER/2017-2021  
FLEETWOOD/SOUTHWIND/2018-2021  
HOLIDAY RAMBLER/VACATIONER/2017-2021

**Mfr's Report Date:** May 26, 2021

**NHTSA Campaign Number:** 21V-395

**Components:**

EQUIPMENT:RECREATIONAL VEHICLE/TRAILER:MATERIALS:FLOORING  
STRUCTURE:BODY

**Potential Number of Units Affected:** 538

**Problem Description:**

REV Recreation Group (REV) is recalling certain 2017-2021 Bounder P Model, Holiday Rambler Vacationer P Model, and 2018-2021 Southwind Model P motorhomes. The floor may have improperly sealed holes that could allow gases such as carbon monoxide to enter the living area.

**Consequence:**

Gases entering the living area increases the risk of an injury and/or death.

**Remedy:**

Dealers will reseal the floor area, free of charge. Owner notification letters are expected to be mailed July 23, 2021. Owners may contact REV customer service at 1-800-509-3417. REV's number for this recall is 210521REV.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

REV Recreation Group's contact for this recall will be Michelle Rice who may be reached by email at [michelle.rice@dot.gov](mailto:michelle.rice@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement