


Sent Message




From Dealer Support dealersupport@revrvgroup.com

Sent Jul 23 2021 7:30 PM in recipient'

To Svc_Campaigns-REVDealerUsers

Subject REV Recreation Group Interim Dealer Notification Recall 210521REV



Hide

To view this message in a browser:
<https://marketing.revrvgroup.com/acton/ct/43072/{{Env.MsgId}}55Bct/{{Env.SrcId}}/{{Env.RecId}}>

Important Interim Safety Recall Dealer Notification

Image:

To see the original, click here:

<https://marketing.revrvgroup.com/acton/ct/43072/{{Env.MsgId}}10Bct/{{Env.SrcId}}/{{Env.RecId}}>

July 23, 2021

TO: ALL REV RECREATION GROUP DEALER PRINCIPALS, SERVICE MANAGERS AND PARTS MANAGERS

SUBJECT: INTERIM NOTIFICATION OF REV RECREATION GROUP RECALL #210521REV
Floor Openings May be Improperly Sealed

REV Recreation Group, Inc., on behalf of its manufacturing center located in Decatur, Indiana, is notifying you of an interim notification campaign regarding a voluntary safety recall conducted in accordance with the United States National Traffic and Motor Vehicle Safety Act and the Canada Motor Vehicle Safety Act.

REV Recreation Group, Inc. has decided that a safety defect relating to motor vehicle safety exists in certain model year(s) 2017-2021 Fleetwood P Model and certain model year(s) 2017-2021 Holiday Rambler Vacationer P Model Class A Gas motorhomes:

2017-2021 Fleetwood Bounder Model 35 P manufactured 11/18/2016-4/5/2021

2018-2021 Fleetwood Southwind Model 36 P manufactured 7/18/2017-12/17/2020

2017-2021 Holiday Rambler Vacationer Model 35 P manufactured 11/21/2016-3/27/2021

WHAT IS THE PROBLEM?

The 35P and 36P Model motorhomes affected by this recall have areas in the floor for wiring harnesses and heat ducts to pass through that were not properly sealed. This condition may allow noxious air or gases to enter the living area, which could cause headache, nausea, loss of consciousness or death over prolonged exposure.

This is the first of two notices you will receive regarding this subject. This notification letter is to inform you of an upcoming Recall as described. The recall remedy is not yet available. A final notification date has not been determined as of the date of this letter. Owners of the above-mentioned motorhomes have been mailed interim recall owner notifications; copies are attached for your information.

WHAT SHOULD YOU DO?

1. If you have one of these vehicles in your inventory: