IMPORTANT SAFETY RECALL

IMPORTANT SAFETY RECALL INTERIM NOTICE

This notice applies to your vehicle

VIN:

Update MBUX Software NHTSA Recall #21V411

July, 2021



- A safety defect exists in your vehicle
- Remedy software is not yet available
- We will contact you again once the software is available

Dear Valued Freightliner Sprinter Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Freightliner Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2019 - 2021 Freightliner Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the concern?



On certain Freightliner Sprinter vans the MBUX multimedia system software might not meet specifications. Under very specific conditions, the MBUX multimedia system might not start and the display might remain black, or could reboot unintentionally after 50 seconds of initial startup. Accordingly, the rearview camera image might not be displayed or the display might be interrupted, which could increase a risk of a crash or injury.

Unfortunately, the software to remedy this are not yet available.

We are working to obtain the necessary software to correct this condition as quickly as possible. When the software become available, we will send you another letter asking you to take your vehicle to an authorized Freightliner Sprinter dealer to have the recall completed free of charge.

Should you have any questions or concerns regarding your vehicle, please contact us at 1-800-367-6372.

A new vehicle identification number (VIN)-based recall lookup tool on our website, offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. Please visit www.freightlinersprinterusa.com/freightliner/owners-resources/recall

We also encourage you to sign up for recall alerts at www.nhtsa.gov/alerts.

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

We apologize for any inconvenience this may have caused and look forward to taking care of this important safety issue immediately.

Sincerely, Daimler Vans USA



IMPORTANT SAFETY RECALL

Additional Information for Owners:

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

									IMPORTANT									VIN:											
	r any r LOSED n.																												
	EXPO LEAS SCRA SOLE STOL OTHI	E, VE APPE) .EN	HIC	LE R	ETU	RNE	E D			_																			
	NEW OR MY N										1						T			T									
Lac	t Nam	o Fir	c+ No	mo																				<u> </u>	<u> </u>				
Las	l Naiii	ie, rii	st iva	me			ı	1	1		1			1	1	1	I	1		1		1		т—		_		l I	
Stre	eet						ı	ı	ı		ı	1	1		1	1		1								Apt		1	
City																					State	9		ZIP					
Em	ail Ad	dress						ı	ı		ı		ı		1	1				ı					.1			I I	
															7														
Phone (numbers only)						1													1										
 Dat	 e								 S	igna	ture	 :																	

