

# Part 573 Safety Recall Report

## 21V-429

**Manufacturer Name :** Trails West Manufacturing of Idaho, Inc.

**Submission Date :** AUG 13, 2021

**NHTSA Recall No. :** 21V-429

**Manufacturer Recall No. :** NR



### Manufacturer Information :

### Population :

**Manufacturer Name :** Trails West Manufacturing of Idaho, Inc.

**Number of potentially involved :** 1

**Address :** 65 North 800 East

**Estimated percentage with defect :** 100 %

PO Box 67 Preston ID 83263

**Company phone :** 208 852 2200

### Vehicle Information :

**Vehicle 1 :** 2020-2020 Trails West Sierra 4H 15x19 LQ

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Dometic sent out a list of units that were part of their recall. We have reviewed the unit and found that we had one unit with the recall oven in it, the Trailer was in a Dealers stock.

**Production Dates :** JAN 01, 2020 - JAN 31, 2020

**VIN Range 1 : Begin :** 49SH74428LP073350 **End :** 49Sh74428LP073350 ☐ Not sequential

### Description of Defect :

**Description of the Defect :** Dometic recall 20E-071. In the Dometic gas oven part #R1731-BBPFBD, A gas leak may occur at the joint between gas saddle valve and the manifold under the burner surface. The leak is believed to be an issue of over tightening the saddle valve.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Oven saddle valve o ring could leak gas, and could increase the risk of fire.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** Increased risk of fire in or around oven.

### Involved Components :

Component Name 1 : RV Oven

Component Description : Saddle Valve Oring

Component Part Number : R1731-BBPFBO

### Supplier Identification :

#### Component Manufacturer

Name : Dometic Corporation

Address : 5155 Verdant Dr.

Elkhart 46516

Country : NR

### Chronology :

Recall letter received from Dometic November 12 2020 , Trails West then went through all records of Trailers that have received ovens in recall dates 4/2/2019 through 6/3/2020 this was all done 1/11/2021. One Trailer was found with a Oven with the recall issue in it. Dealer was notified no to sale Trailer until repair was determined 1/18/2021 All test of of the Saddle Valve was done By Dometic and Trails West is not aware of the Test results.

### Description of Remedy :

Description of Remedy Program : New saddle Valve sent out by Dometic to Dealer for replacement. New burner seals (O rings) and igniter switch

How Remedy Component Differs from Recalled Component : New O ring were heavier O rings

Identify How/When Recall Condition was Corrected in Production : The correction in production was done By Dometic. Trails West is not aware of the correction in Demetic production process.

### Recall Schedule :

Description of Recall Schedule : The only triler that had the recalled oven in it was on a dealers yard, and had not been sold to a retail customer. Replacement parts were sent from Dometic to Dealer before trailer was sold, and repaired.

Planned Dealer Notification Date : JUN 04, 2021 - JUN 04, 2021

Planned Owner Notification Date : NR - NR

\* NR - Not Reported