



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 17, 2021

Mr. Mike Becker
Director of Corporate Compliance
Forest River, Inc.
2324 Century Drive
Goshen, IN 46528

NEF-107KL
21V-444

Subject: LP/CO Detector Installed Incorrectly

Dear Mr. Becker:

This letter serves to acknowledge Forest River, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

EAST TO WEST/ALTA/2021

Mfr's Report Date: June 11, 2021

NHTSA Campaign Number: 21V-444

Components:

EQUIPMENT

Potential Number of Units Affected: 10

Problem Description:

Forest River, Inc. (Forest River) is recalling certain 2021 East to West Alta Travel Trailers. The LP/CO detector was installed in the incorrect location.

Consequence:

Incorrect placement of the LP/CO detector can impair the detection of a propane leak, increasing the risk of a fire, or the presence of carbon monoxide, increasing the risk of injury.

Remedy:

Dealers will install a new detector in the correct location, free of charge. Owner notification letters are expected to be mailed on July 20, 2021. Owners may contact Forest River customer service at 1-574-264-6664. Forest River's number for this recall is 501-1366.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Forest River, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement