

Part 573 Safety Recall Report

21V-480

Manufacturer Name : Winnebago Industries, Inc.

Submission Date : JUN 25, 2021

NHTSA Recall No. : 21V-480

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Winnebago Industries, Inc.

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 1,566

Estimated percentage with defect : 2 %

Vehicle Information :

Vehicle 1 : 2021-2022 Winnebago Solis, Travato, Ekko

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Freedman shipment records compared to Winnebago production records

Production Dates : MAY 12, 2020 - MAR 30, 2021

VIN Range 1 : Begin : NR **End :** NR

Not sequential

Description of Defect :

Description of the Defect : The seat belt retractors may lock up when the vehicle is on a slight incline.

FMVSS 1 : 208 - Occupant crash protection

FMVSS 2 : 209 - Seat belt assemblies

Description of the Safety Risk : Seat belt retractor could lock up when vehicle is on a slight incline and the seating occupant could be confined or trapped.

Description of the Cause : The seat retractors on a double seat may have been incorrectly located on the seat, i.e. the retractor was assembled to the wrong seating position

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : NR

Component Description : Dual seat

Component Part Number : goes-46183-2pflipss

Supplier Identification :

Component Manufacturer

Name : Freedman Seating Company

Address : 4545 W Augusta Blvd

Chicago Illinois 60465

Country : United States

Chronology :

3-15-21 Customer complaint about seatbelt lockup when on incline

3-15-21 Contacted Freedman

4-20-21 Several customers complaints

4-26-21 Meetings with Freedman

6-8-21 Freedman tells us they are going to file recall with NHTSA

6-22-21 Winnebago received recall notice from Freedman

6-25-21 Winnebago submitted 573 notice on NHTSA portal

Description of Remedy :

Description of Remedy Program : Freedman will provide a seat inspection and repair procedure to Winnebago to mail out to our customers

How Remedy Component Differs from Recalled Component : None

Identify How/When Recall Condition was Corrected in Production : The parts are coming in correct, however QC is checking to make sure the retractors are installed in the right location.

Recall Schedule :

Description of Recall Schedule : TBD

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported