#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 21V-480

Manufacturer Name: Winnebago Industries, Inc.

**Submission Date:** JUL 30, 2021 NHTSA Recall No.: 21V-480 Manufacturer Recall No.: NR



#### **Manufacturer Information:**

**Population:** 

Manufacturer Name: Winnebago Industries, Inc.

Address: PO BOX 152

605 W. Crystal Lake Rd. Forest City IA

50436

Company phone: 1-641-585-3535

Number of potentially involved: 1,566 Estimated percentage with defect: 2 %

#### **Vehicle Information:**

Vehicle 1: 2021-2022 Winnebago Solis, Travato, Ekko

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: Freedman shipment records compared to Winnebago production records

Production Dates: MAY 12, 2020 - MAR 30, 2021

VIN Range 1: Begin: NR End: NR Not sequential

#### **Description of Defect:**

Description of the Defect: The seat belt retractors may lock up when the vehicle is on a slight incline.

FMVSS 1: 208 - Occupant crash protection

FMVSS 2: 209 - Seat belt assemblies

Description of the Safety Risk: Seat belt retractor could lock up when vehicle is on a slight incline and the

seating occupant could fee confined or trapped.

Description of the Cause: The seat retractors on a double seat may have been incorrectly located on the

seat, i.e. the retractor was assembled to the wrong seating position

Identification of Any Warning NR

that can Occur:

# **Involved Components:**

Component Name 1: NR

Component Description: Dual seat

Component Part Number: goes-46183-2pflipss

# **Supplier Identification:**

#### **Component Manufacturer**

Name: Freedman Seating Company

Address: 4545 W Augusta Blvd

Chicago Illinois 60465

**Country: United States** 

# **Chronology:**

3-15-21 Customer complaint about seatbelt lockup when on incline

3-15-21 Contacted Freedman

4-20-21 Several customers complaints

4-26-21 Meetings with Freedman

6-8-21 Freedman tells us they are going to file recall with NHTSA

6-22-21 Winnebago received recall notice from Freedman

6-25-21 Winnebago submitted 573 notice on NHTSA portal

## **Description of Remedy:**

Description of Remedy Program: Freedman will provide a seat inspection and repair procedure to

Winnebago to mail out to our customers (note all these units are still

under warranty)

How Remedy Component Differs None

from Recalled Component:

Identify How/When Recall Condition The parts are coming in correct, however QC is checking to make sure the

was Corrected in Production: retractors are installed in the right location.

### **Recall Schedule:**

Description of Recall Schedule: TBD

Planned Dealer Notification Date : JUL 30, 2021 - JUL 30, 2021 Planned Owner Notification Date : JUL 30, 2021 - JUL 30, 2021

Part 573 Safety Recall Report	21V-480	Page 3
* NR - Not Reported		
The information contained in this report was submitted	Inursuant to 49 CFR 8573	