


CONDITION OF CONCERN

Due to an improper material specification, the plastic Mazda logo may become brittle. Plastic fragments of the shattered logo may hit occupants during a normal air bag deployment in a crash, increasing the possibility of serious injury to occupants.



OUTLINE OF REPAIR

The air bag module cover will be replaced with an improved part. Please refer to the Repair Procedure document on MGSS for further details.

SUBJECT VEHICLES

Model	Subject VIN range	Subject production date range
2004-2007 Mazda3	JM1 BK**** 41 100046 - 217952 JM1 BK**** 51 192363 - 350581 JM1 BK**** 61 400001 - 546533 JM1 BK**** 71 600001 - 601664	From July 24, 2003 through June 22, 2006

The asterisk symbol "*" can be any letter or number.

OWNER NOTIFICATION

Mazda will notify U.S. owners by first class mail no later than August 28, 2021.

PARTS INFORMATION

Description	Part Number	Quantity	Note
Air Bag Module Cover	BPYK-57-K00	1	
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)

WARRANTY CLAIM PROCESSING INFORMATION

	Air Bag Module Cover Replacement
Process Number	AM026A
Symptom Code	99
Damage Code	99
Causal Part Number	BPYK-57-K00
Quantity	1
Labor Operation Number	XXT53XRX
Labor Hours	0.6 hrs.

RENTAL CAR INFORMATION

Mazda recommends the usage of the MCVP loaner vehicle when available. If all MCVP loaner vehicles are in use and unavailable, and the customer needs a rental car, then use your local rental facility and offer a rental car. Be sure that every effort is made to repair the car within one business day or less, so the next customer can receive the same experience.

Rental Car Warranty Claim Information

	MCVP Vehicle Preferred	Rental Agency Vehicle
Warranty Type Code	N/A MCVP does not require claim submission	A
Symptom Code		99
Damage Code		99
Part Number Main Cause		5555-49-21GR
Part Quantity		0
Labor Operation Code		MM024XRX
Labor Hours		0
Sublet – Rental Car		
Sublet Invoice Number		Number from Rental Invoice or Dealer Purchase Order
Sublet Type Code		Enter "Z9" (other)
Sublet Amount		Up to \$30.00 per day for the number of days customer had rental car
Sublet Text		Number of days rental car was supplied to customer

Rental expenses exceeding the two-day limit will require prior Warranty Department Authorization, as outlined in the Mazda Rental Car Reimbursement Program policy.