

## CAMPAIGN LAUNCH STATUS

### N609 SAFETY RECALL - SEAT TRACK END STOP DAMAGE



SAFETY RECALL N609 FRONT SEAT TRACK – DEFENDER 90	
AFFECTED MODELS	21MY DEFENDER 90 WITH MANUAL SEATS
VOLUME AFFECTED	603 USA 66 CAN
REPAIR	On vehicles with manually adjustable left and right front seats, the front seat track end stop bracket may become deformed. Deformed seat track end stop brackets may allow the seat to latch further forward than intended by design and may allow reduced seat strength in the event of a crash. Both front seats on affected vehicles will require replacement of the seat tracks with a modified part.
REPAIR TIME	1.0 hrs + DIDO
TARGET CAMPAIGN LAUNCH	Retailer recall notification and stop sale July 15 <sup>th</sup> , 2021. NAS21.07.017 CAN and NAS21.07.018 USA. Parts now available. Launch due by Sept 21 <sup>st</sup> , 2021
Notes	25 unsold units in retailer stock. Requires locally sourced Loctite 243 thread lock

