News Channel Update

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Recall Campaign Initial Notification		
Replace LED Headlamp	DATE: July 12, 2021	
MY18-21 GLE-Class, C-Class, A-Class, GLB-Class	JATE: July 12, 2021	
(167, 205, 177, 247 platform)		

IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



News Channel Update

Vehicle Compliance & Analysis

	<u> </u>			
Campaign No.:	NHTSA ID	Campaign Desc. :	Replace LED Headlamp	
TBA	21V509	21P2197408	Replace LED Headlamp	
This is to notify you of a new Recall Campaign to replace the LED headlamp on 1,467 Model Year ("MY") 2018-2021 GLE-Class (167 platform), C-Class (205 platform), A-Class (177 platform) and GLB-Class (247 platform) vehicles. The recall campaign will be visible on the www.safercar.gov website and may generate questions from customers. Affected VINs will be flagged in VMI as "PENDING" on July 12, 2021.				
Background				
Issue		Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2018-2021 GLE-Class (167 platform), C-Class (205 platform), A-Class (177 platform) and GLB-Class (247 platform) vehicles with "LED" headlamps where a recalibration of the headlamp was necessary due to a repair, the adjustment of the headlamps might not meet current production specifications or fulfill the requirements of FMVSS 108 (Lamp, Reflective Devices and Associated equipment - §571.108 S10.14.6). In this case, the light intensity of the high beam, low beam, and the model specific turn signal indicator may not conform to the requirements of FMVSS 108, which could increase the risk of a crash.		
What We're Doing		An authorized Mercedes-Benz dealer will replace the LED headlamps on the affected vehicles.		
Parts		Remedy is not available at this time. An additional notification will be sent once the remedy is available.		
Vehicles Affected				
Vehicle Model Year(s)		2018-2021		
Vehicle Model		GLE-Class, C-Class, A-Class, GLB-Class		
Vehicle Populations				
Total Recall Population	1	1,467		
Total Vehicles in Deale	r Inventory	2		
Given this notice, it is a violation of Federal law for a dealer to sell or lease any new MY18-21 GLE-Class, C-Class, A-Class, GLB-Class vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Once the remedy is available, the vehicles will be flagged as "OPEN" and Work Instructions will be available in Star TekInfo. Once the repair is complete the vehicle may be sold or leased. Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired. As a matter of normal service process, please check for other repair measures which might be applicable to the vehicle(s)				
Additionally, given this notice, it is <u>a violation of Federal Law</u> for <u>car rental companies</u> to rent new MY18-21 GLE-Class, C-Class, A-Class, GLB-Class vehicles covered by this notification until the vehicle has been repaired.				
Next Steps/Notes				
Customer Notification	Timeline	Customer letters will be ma	ailed after the remedy becomes available.	
AOMS/SOMS	AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.			
Rental Fleet Partners		-	les in your fleet. Please contact your respective MBUSA fleet nformation and next steps. For repairs, please contact your	



preferred MBUSA dealer.

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.