

July 21, 2021

Ms. Larissa Stoffels Exec Mgr, Vehicle Safety Daimler Trucks North America, LLC 4747 N. Channel Ave Portland, OR 97217

Subject: Rear Suspension Leaf Spring Eye May Break

Dear Ms. Stoffels:

This letter serves to acknowledge Daimler Trucks North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: FCCC/MT45/2022

Mfr's Report Date: July 2, 2021

NHTSA Campaign Number: 21V-510

Components: SUSPENSION:REAR:SPRINGS

Potential Number of Units Affected: 79

Problem Description:

Daimler Trucks North America, LLC (DTNA) is recalling certain 2022 Freightliner Custom Chass MT45 Chassis. The leaf spring eye on the rear suspension may be undersized, which could result in it breaking and detaching from the vehicle.

Consequence:

A detached leaf spring eye can create a road hazard, increasing the risk of a crash.

Remedy:

The remedy is currently under development. Owner notification letters are expected to be mailed August 30, 2021. Owners may contact DTNA's customer service at 1-800-547-0712. DTNA's number for this recall is FL-895.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107MR 21V-510

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Daimler Trucks North America, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alae Andy,

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

