



December, 2021

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: 21S34 - BATTERY CABLE CONTACT BISG/AC

What is the issue? On your vehicle, the battery cable wire harness may not be properly secured, allowing contact with the A/C compressor pulley.

Over time, the A/C pulley may rub through the wire harness insulation and contact the unfused positive battery (B+) circuit, which may result in a short circuit and potential fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: owner.lincoln.com.

Thank you for your attention to this very important matter.

December de, 2021

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en su 2020 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 21S34 - BISG/CA DEL CONTACTO DEL CABLE DE LA BATERIA

¿Cuál es el problema? En su vehículo, el arnés de la batería podría no estar correctamente asegurado, lo cual hace posible el contacto con la polea del compresor del A/C.

Con el paso del tiempo, la polea del A/C podría rozar en el aislamiento del arnés y generar contacto con el circuito positivo de la batería (B+) sin fusible, lo cual podría generar un cortocircuito y un posible incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: owner.lincoln.com.

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0012724 A / 000000000000250 / 250



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

