

July 21, 2021



Recall Notice

Recall #TS-0039 : Safety Cable Replacement

Condition: Need to replace equipped Class 2 safety cables with Class 4 safety cables.

Models Affected: Model Year '21 and '22 RT198PP non-brake and RT198PPB brake trailers

Time Allowed: .25 hour

Recall Information

DESCRIPTION OF CONCERN:

Affected units are equipped with Class 2 safety cables. These need to be replaced with Class 4 safety cables.

REQUIRED PART NUMBER:

Quantity of 2:

186881-CABLE,BLK PVC,S HOOK,CLS IV

VERIFICATION PROCESS:

N/A

CORRECTIVE ACTION:

See instructions below. Order the necessary parts on the dealer portal and file a claim for parts and labor once the repairs are complete.

View the complete recall details from the recall tab on the Dealer Portal

NOTE THAT INTERNET EXPLORER MUST BE USED TO ENABLE LINKS TO VIEW DOCUMENTS

Replace Safety Cables

RT198PP non-brake

and

RT198PPB brake trailers

Use White River Marine Group part number
186881 (class 4 safety cable) for replacement

Total time allowed 15 minutes per trailer

Tools needed:

1 - $\frac{3}{4}$ " open end wrench

1 - $\frac{3}{4}$ " socket – ratchet

- Remove the class 2 – 3500lb cable by holding the bolt inside the tongue with a $\frac{3}{4}$ " and a $\frac{3}{4}$ " socket wrench to remove the nut.





Replace the cable with a class 4 - 7,000lb.

- Reinstall the washer over the cable and then thread on the nut. Tighten the nut by holding the bolt inside the tongue with a $\frac{3}{4}$ " wrench and a socket wrench on the nut. Do not overtighten the nut. You should be able to pivot the cable on the bolt with a little resistance.

