

Recall Quarterly Report

21V-558

Manufacturer Name : Suzuki Motor USA, LLC
NHTSA Recall No. / MFR Recall No. : 21V-558 / 2A97
Recall Subject : Fuel Hose Assembly May Leak Fuel
Owner Notification Beginning Date : AUG 20, 2021
Owner Notification End Date: AUG 20, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 15, 2021	2021-3	270	52	5	1

This Document Last Updated : OCT 18, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.