

Part 573 Safety Recall Report

21V-558

Manufacturer Name : Suzuki Motor USA, LLC

Submission Date : JUL 22, 2021

NHTSA Recall No. : 21V-558

Manufacturer Recall No. : 2A97



Manufacturer Information :

Manufacturer Name : Suzuki Motor USA, LLC

Address : 3251 East Imperial Highway
Brea CA 92821-6795

Company phone : 714-996-7040

Population :

Number of potentially involved : 270

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2020 Suzuki UH200

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The recall population was determined based on production records. All 2018 and 2019 model year vehicles are included.

Production Dates : AUG 17, 2018 - NOV 25, 2019

VIN Range 1 : Begin : MLCCH41A3K1600001 **End :** MLCCH41A0K1600120

☐ Not sequential

VIN Range 2 : Begin : MLCCH41A1L1600001 **End :** MLCCH41A7L1600150

☐ Not sequential

Description of Defect :

Description of the Defect : The fuel hose assembly which is comprised of a flexible fuel hose that is press-fit onto barbed metal attachment pipes with the hose secured by crimped metal clamping bands, may leak fuel at the joining points with the metal attachment pipes.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If fuel leaks from the fuel hose assembly, risk of fire is increased.

Description of the Cause : Fuel hose of affected vehicles may have been manufactured using a resin-based extrusion mandrel that was larger than the inspection control value of the supplier. Fuel hose produced under this condition may have an internal diameter that is larger than the inspection control value of the supplier and may have an improperly loose connection with the metal fuel hose connection pipes.

Identification of Any Warning that can Occur : Fuel smell after a period of vehicle shutdown.

Involved Components :

Component Name 1 : Hose, fuel

Component Description : Fuel supply hose assembly

Component Part Number : 15810-29K00

Supplier Identification :**Component Manufacturer**

Name : TECHNOMEIJI RUBBER (THAILAND) CO.,LTD.

Address : Amata Nakorn Industrial Estate

700/388 Moo 6 Tambol Donhuaroh Amphur Muang, Chonburi Foreign States 20000

Country : Thailand

Chronology :

The chronology is attached as a separate document.

Description of Remedy :

Description of Remedy Program : The fuel hose assembly will be replaced with a countermeasure part. The plan for customer reimbursement is supplied as a separate document.

How Remedy Component Differs from Recalled Component : The countermeasure part uses fuel hose that has the correct internal diameter specification.

Identify How/When Recall Condition was Corrected in Production : From May 18, 2020, the fuel hose supplier has implemented new quality control measures that replace previous batch sample inspection of hoses to inspection of 100% of production.

Recall Schedule :

Description of Recall Schedule : The notification schedule shown is a current estimate. Suzuki will provide notification of any schedule changes as necessary.

Planned Dealer Notification Date : AUG 13, 2021 - AUG 13, 2021

Planned Owner Notification Date : AUG 20, 2021 - AUG 20, 2021

* NR - Not Reported