

IMPORTANT SAFETY RECALL

Audi of America, Inc.



<MONTH YEAR>

<CUSTOMER NAME>

<CUSTOMER ADDRESS>

<CUSTOMER CITY STATE ZIPCODE>

This notice applies to your vehicle: <MODEL YEAR> <BRAND> <CARLINE>, <VIN>

NHTSA: 21V569

Subject: Safety Recall 47R1 – Brake Pressure Unit

Dear Audi Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Audi has decided that a defect, which relates to motor vehicle safety, exists in certain 2020-2021 model year Audi vehicles. Our records show that you are the owner of a vehicle affected by this action.

Audi of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326
+1 800 253 2834
www.audiusa.com

What is the issue? The rotor and the shaft of the integrated brake system may not have been welded to specifications. During a hard braking maneuver, the ABS hydraulic control unit rotor and shaft could separate, which could lead to a reduction in braking assistance (brake boost) as well as a loss of Antilock Brake System (ABS) functionality and Electronic Stability Control (ESC). Full mechanical braking is still available. During a hard braking maneuver, a reduction in brake assistance (brake boost) could lead to an extended stopping distance. In combination with a loss of ABS and ESC functionalities, this could increase the risk of a crash.

What will we do? To correct this defect, your authorized Audi dealer will replace the brake pressure unit. This work will take about four hours to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.

What should you do? Please contact your authorized Audi dealer without delay to schedule this recall repair. For your convenience, you can also visit www.audiusa.com and click on the "Find a Dealer" link to locate a dealer near you and schedule this service.

Precautions you should take A failure of the brake booster will be indicated by a warning message in the vehicle's instrument cluster. Should this occur, customers are advised to contact their authorized Audi dealer without delay and make arrangements to have the vehicle serviced.

Lease vehicles and address changes If you are the lessor and registered owner of the vehicle identified in this action, the law requires you to forward this letter immediately via first-class mail to the lessee within ten (10) days of receipt. If you have changed your address or sold the vehicle, please fill out the enclosed prepaid Owner Reply card and mail it to us so we can update our records.

IMPORTANT SAFETY RECALL



Can we assist you further?

If your authorized Audi dealer fails or is unable to complete this work free of charge within a reasonable time, please contact Audi Customer Experience at 1-800-253-2834 or via our “Contact Us” page at www.audiusa.com.

Checking your vehicle for open Recalls and Service Campaigns

To check your vehicle's eligibility for repair under this or any other recall/service campaign, please visit the **Recall/Service Campaign Lookup** tool at www.audiusa.com and enter your Vehicle Identification Number (VIN).

If you still cannot obtain satisfaction, you may file a complaint with: The Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We apologize for any inconvenience this matter may cause; however we are taking this action to help ensure your safety and continued satisfaction with your vehicle.

Sincerely,

Audi Customer Protection