

Part 573 Safety Recall Report

21V-583

Manufacturer Name : NRC Modifications, Inc.

Submission Date : AUG 19, 2021

NHTSA Recall No. : 21V-583

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : NRC Modifications, Inc.

Address : 51045 GREENFIELD PARKWAY
MIDDLEBURY IN 46540

Company phone : 574-825-3646

Population :

Number of potentially involved : 2

Estimated percentage with defect : 100 %

Vehicle Alterer Information :

Vehicle 1 : 2019-2020 NRC Motorhome Motorhome

Descriptive Information : Built on a Freightliner Cascadia and Wester Star, both are equipped with Dometic stoves that are listed on the recall.

Production Dates : MAY 01, 2018 - JUL 09, 2020

Description of Defect :

Description of the Defect : The smell of "gas" may occur and the occupant may attempt to tighten the bolts and if they over tighten to muc may cause damage to the o ring between the saddle valve and manifold. which could cause a continuous leak.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Over tightening on the bolts could cause a gas leak which may ignite and cause a fire

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name : Dometic Stove 3 burner lp stove with an oven

Component Description : Model R2131-BBPFBO

Component Part Number : S/N# 83399608

Component Name : Dometic 3 burner lp stove

Component Description : S31-SPFMO

Component Part Number : S/N# SU82600439

Supplier Identification :

Component Manufacturer

Name : Dometic

Address : 5155 Verdant Drive
Elkhart Indiana 46516

Country : United States

Chronology :

NRC was contacted by NHTSA to inform us that Dometic has a stove recall. Dometic identified our company as a purchaser of this equipment. The date for NHTSA was June 1, 2021 for a notice. NRC was later contacted by Dometic July 21, 2021.

Description of Remedy :

Description of Remedy Program : Dometic has a kit, with gaskets, washers, thread lock bolts, and round orange labels that are to be applied to the product for the recall. The remedy will be available for installation at a Dometic authorized service center. Contact the Dometic hotline at 888-943-4905 or 574-389-3713 and they will help with finding a service center.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dometic has a recall management company, Stericycle to assist with the recall notification process. NRC provided them with the dealers name and addresses VIN# etc. as of July 27, 2021.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported