



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 5, 2021

Mr. Troy Niswonger
Regulatory Compliance Manager
Entegra Coach
903 South Main Street
P.O. Box 460
Middlebury, IN 46540

NEF-107KL
21V-591

Subject: High Pressure Fuel Rail Assembly May Leak Fuel

Dear Mr. Niswonger:

This letter serves to acknowledge Entegra Coach's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ENTEGR/A/NTHEM/2018-2022
ENTEGR/A/ASPIRE/2018-2022
ENTEGR/A/INSIGNIA/2018-2022
ENTEGR/A/REATTA XL/2018-2022

Mfr's Report Date: July 30, 2021

NHTSA Campaign Number: 21V-591

Components:

FUEL SYSTEM, DIESEL:FUEL INJECTION SYSTEM:FUEL RAIL

Potential Number of Units Affected: 1,284

Problem Description:

Entegra Coach (Entegra) is recalling certain 2018-2022 Anthem, Aspire, Insignia, and Reatta XL Class A vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak.

Consequence:

A fuel leak in the presence of an ignition source increases the risk of a fire.

Remedy:

Entegra will work with Spartan and Cummins to inspect the rail threads and fuel lines, and replace the rail as necessary, free of charge. Cummins began to notify owners July 30, 2021. Owners may contact Entegra Coach customer service at 1-800-517-9137.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Entegra Coach's contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement