AUDI DEALER COMMUNICATION

Repair Available - Compliance Recall 69CS / ALR Seat Belt Retractors

This notice is for:	 ✓ Dealer F ✓ General ✓ Sales Ma 	Manager	 ✓ Service Ma ✓ Parts Man ✓ Service Ac 	ager 🗸 Technicians	ninistrator				
Date:	August 12, 2021								
Issue:	Autoliv has determined that certain seat belt assemblies do not comply with regulatory requirements. In these certain seat belt assemblies, the automatic locking retractor (ALR) function may deactivate early before the webbing is fully retracted.								
	The ALR function is required by regulatory requirement. This noncompliance does not impact the compliance or functionality of the seat belt assemblies with respect to their normal use by adult passengers or use of the LATCH system to secure child restraint seats.								
	With child restraint seats for which the vehicle owner elects to use the seat belt to secure the child restraint seat instead of the LATCH system, if the seat belt is not lockable so that the seat belt assembly can be used to tightly secure the child restraint seat, there is an increased risk of injury in a crash to the occupant of the child restraint seat.								
Precautions	A vehicle owner who elects to use the seat belt instead of the LATCH system to secure a child restraint seat will notice that the seat belt is not locked and the audible clicking noise made when the ALR function is activated stops well before the seat belt webbing is fully retracted.								
Repair: Parts	 REPAIR AVAILABLE – August 13, 2021 - Inspect and, if necessary, replace an affected seat belt(s). See ELSA/ServiceNet for complete repair & claiming instructions Check daily campaign open inventory report or OMD for affected vehicles in inventory Repair every affected inventory vehicle <u>before delivery to consumers</u>. 								
Department:	Due to the very low replacement rate expected under this recall, there will be no parts allocation. See the campaign circular for complete details.								
Affected	Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count				
Vehicles	USA	2021	2021	A4 ALLROAD	139				
	USA	2021	2021	A4 SEDAN	3,109				
	USA	2021	2021	A5 CABRIOLET	97				
	USA	2021	2021	A5 COUPE	77				
	USA	2021	2021	A5 SPORTBACK	1,446				
	USA	2021	2021	A6 ALLROAD	261				
	USA	2021	2021	A6 SEDAN	2,076				
	USA	2021	2021	A7	415				

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.

Audi Customer Protection

udi

USA	2021	2021	A8	306
USA	2021	2021	E-TRON QUATTRO	2,495
USA	2021	2021	E-TRON SPORTBACK QUATTRO	700
USA	2021	2021	Q3	8,781
USA	2021	2021	Q5	10,217
USA	2021	2021	Q5 SPORTBACK	1,161
USA	2021	2021	Q7	6,270
USA	2021	2021	Q8	1,546
USA	2021	2021	RS5 COUPE	181
USA	2021	2021	RS5 SPORTBACK	627
USA	2021	2021	RS6 AVANT	304
USA	2021	2021	RS7	313
USA	2021	2021	RSQ8	232
USA	2022	2022	S3 SEDAN	24
USA	2021	2021	S4 SEDAN	325
USA	2021	2021	S5 CABRIOLET	41
USA	2021	2021	S5 COUPE	48
USA	2021	2021	S5 SPORTBACK	385
USA	2021	2021	S6 SEDAN	166
USA	2021	2021	S7	132
USA	2021	2021	S8	27
USA	2021	2021	SQ5	704
USA	2021	2021	SQ5 SPORTBACK	278
USA	2021	2021	SQ7	389
USA	2021	2021	SQ8	199
CAN	2021	2021	A4 ALLROAD	79
CAN	2021	2021	A4 SEDAN	223
CAN	2021	2021	A5 CABRIOLET	11
CAN	2021	2021	A5 COUPE	21
CAN	2021	2021	A5 SPORTBACK	117
CAN	2021	2021	A6 ALLROAD	23
CAN	2021	2021	A6 SEDAN	27
CAN	2021	2021	A7	12
CAN	2021	2021	A8	13
CAN	2021	2021	E-TRON QUATTRO	190
CAN	2021	2021	E-TRON SPORTBACK QUATTRO	101
CAN	2021	2021	Q3	2,566
CAN	2021	2021	Q5	2,069
CAN	2021	2021	Q5 SPORTBACK	205
CAN	2021	2021	Q7	424

2021	2021	Q8	108
2021	2021	RS5 COUPE	26
2021	2021	RS5 SPORTBACK	72
2021	2021	RS6 AVANT	85
2021	2021	RS7	29
2021	2021	RSQ8	42
2022	2022	S3 SEDAN	2
2021	2021	S4 SEDAN	57
2021	2021	S5 CABRIOLET	11
2021	2021	S5 COUPE	47
2021	2021	S5 SPORTBACK	98
2021	2021	S6 SEDAN	3
2021	2021	S7	7
2021	2021	S8	5
2021	2021	SQ5	256
2021	2021	SQ5 SPORTBACK	171
2021	2021	SQ7	58
2021	2021	SQ8	40
	2021 2021 2021 2021 2021 2022 2021 2021	2021	2021 2021 RS5 COUPE 2021 2021 RS5 SPORTBACK 2021 2021 RS6 AVANT 2021 2021 RS7 2021 2021 RS7 2021 2021 RSQ8 2022 2022 S3 SEDAN 2021 2021 S4 SEDAN 2021 2021 S5 CABRIOLET 2021 2021 S5 SPORTBACK 2021 2021 S5 SPORTBACK 2021 2021 S5 SPORTBACK 2021 2021 S6 SEDAN 2021 2021 S6 SEDAN 2021 2021 S6 SEDAN 2021 2021 S6 SEDAN 2021 2021 S8 2021 2021 S8 2021 2021 SQ5 2021 2021 SQ5 SPORTBACK 2021 2021 SQ5 2021 2021 SQ7

*Counts reflect overall population; some vehicles may have already been repaired. Check Campaigns/Actions screen in Elsa <u>on the day of repair</u> to verify that a VIN qualifies for repair under this action. Elsa is the <u>only</u> valid campaign inquiry & verification source.

Notes:

٠

Schedule owner repairs immediately

• Owner mailing – August 2021

IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

<u>New Vehicles in Dealer Inventory</u>: It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

<u>Pre-Owned Vehicles in Dealer Inventory:</u> Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

-END OF MESSAGE-