

VOLKSWAGEN DEALER COMMUNICATION - USA

Repair Available - Compliance Recall 69CQ / Rear Outboard Seat Belts

This notice is for:

- Dealer Principal
- ✓ Service Manager
- Warranty Administrator

✓ General Manager

Sales Managers

- ✓ Parts Manager
 - agoi
- Service Consultant
- Technicians

Date:

August 12, 2021

Issue:

Vehicles may have received an incorrect seat belt assembly not released for the U.S. market. Only the outer rear seats are potentially affected. The potentially incorrect seat belt assemblies do not have the automatic locking retractor (ALR) function required by FMVSS 208 implemented.

This noncompliance does not impact the compliance or functionality of the seat belt assemblies with respect to their normal use by adult passengers or use of the LATCH system to secure child restraint seats. With child restraint seats for which the vehicle owner elects to use the seat belt to secure the child restraint seat instead of the LATCH system, if the seat belt is not lockable so that the seat belt assembly can be used to tightly secure the child restraint seat, there is an increased risk of injury in a crash to the occupant of the child restraint seat.

Repair:

- REPAIR AVAILABLE August 13, 2021 / Inspect and, if necessary, replace any incorrect seat belt assembly.
- See ELSA/ServiceNet for complete repair & claiming instructions
- Check both the daily Campaign Open Inventory report <u>and</u> OMD for affected vehicles in inventory. Verify OPEN status in ELSA <u>on the day of repair</u>.
- Repair every affected inventory vehicle <u>before delivery to consumers</u>.

Parts Department:

There will be no parts allocation. Please reference the Repair Projection Tool (below) to view your potential VIN population. Do not order parts unless they are absolutely needed! The expected need for parts is less than 1%. Ordering parts unnecessarily will cause delays.

Affected Vehicles

Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
USA	2021	2021	ID4	12,060

^{*}Counts reflect overall population; some vehicles may have already been repaired. Check Campaigns/Actions screen in Elsa <u>on the day of repair</u> to verify that a VIN qualifies for repair under this action. Elsa is the <u>only</u> valid campaign inquiry & verification source.

Notes:

- Schedule owner repairs immediately
- Owner mailing August 2021

<u>U.S.A.:</u> Loaner/rental coverage cannot be claimed under this action. However, loaner/rental may be covered under the Alternate Transportation Program. Please refer to the Volkswagen Warranty Policy and Procedures Manual for loaner claims information and reimbursement details.

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.

IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

New Vehicles in Dealer Inventory: It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

<u>Pre-Owned Vehicles in Dealer Inventory:</u> Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

-END OF MESSAGE-