TOPIC	TYPE	RECAL L CODE	QUESTION	ANSWER
Safety			What vehicles are included	Country Beginning Ending Vehicle Model Year Model Year
Recaĺl 24HH	Safety Recall	24HH	in Safety Recall 24HH?	USA 2022 2022 TAOS
241111	ricean		What is the safety concern for Safety Recall 24HH?	Vehicles included in this recall are equipped with an all-wheel drive powertrain and have a specific software version installed in the engine control unit that, under specific conditions (high ambient temperatures, high engine load, A/C on), may lead to a stalling condition when coming to a stop. The engine can be immediately restarted manually. An engine that stalls while coming to a stop (20 MPH) may increase the risk of a crash.
			What is the repair for Safety Recall 24HH? When will the repair for Safety Recall 24HH be available?	To correct this defect, your authorized Volkswagen dealer will update the engine control unit (ECU) software. This work will take about an hour to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule. Repairs for this recall have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer.