OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-626

Manufacturer Name: Cottrell, Inc.

Submission Date: OCT 22, 2021

NHTSA Recall No.: 21V-626

Manufacturer Recall No.: 2021 1-Car Reflector



Manufacturer Information:

Manufacturer Name: Cottrell, Inc.

Address: 2125 Candler Road

Gainesville GA 30507

Company phone: 770-532-7251

Population:

Number of potentially involved: 878 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2018-2021 Cottrell 1-Car Carrier

Vehicle Type: TRAILERS
Body Style: OTHER
Power Train: DIESEL

Descriptive Information: A customer contacted Cottrell concerning a citation that it received for lack of reflex

reflectors on the side/rear of the 1-Car Carrier. After a full & thorough investigation, Cottrell determined that all 1-Car Carriers built between 6/18/2018 and 8/9/2021, a total of 878, were missing four (4) side/rear reflex reflectors as required in FMVSS

108.

Production Dates: JUN 18, 2018 - AUG 09, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Noncompliance:

Description of the 1-Car Carriers, a total of 878, were built between June of 2018 and August 9,

Noncompliance: 2021 without reflex reflectors as required in FMVSS 108.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: Non-Compliance with FMVSS 108.

Description of the Cause: 1-Car Carriers, a total of 878, were built between June 18, 2018 and August 9,

2021 without reflex reflectors as required in FMVSS 108.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: Reflex Reflector Kit

Component Description: Side & Rear Reflex Reflector Lights (4 total), cleaning wipe & installation

instructions

Component Part Number: 168756

Supplier Identification:

Component Manufacturer

Name: Cottrell, Inc.

Address: 2125 Candler Road

Gainesville Georgia 30507

Country: United States

Chronology:

A customer contacted Cottrell on Friday 8/6/2021 concerning a citation that it received for lack of reflex reflectors on the side/rear of the 1-Car Carrier. After a full & thorough investigation, Cottrell determined on 8/10/2021 that all 1-Car Carriers, a total of 878, built between 6/18/2018 and 8/9/2021 were missing four (4) side/rear reflex reflectors as required in FMVSS 108, All 1-Car Carriers being built from 8/10/2021 going forward will have the 4 missing reflect reflectors. Absence of the reflex reflectors may increase the risk of a motor vehicle crashing into the 1-Car Carrier due to lessened visibility.

Description of Remedy:

Description of Remedy Program: Cottrell is finalizing an Installation Guide with pictures/diagrams and specific instructions on how to install the 4 missing Reflex Reflectors on the 1-Car Carriers. Cottrell will provide all parts needed free of charge to the customer, and will reimburse labor costs up to one-half hour per unit. If any customer incurred costs to install the 4 missing reflectors prior to notice of this recall, which Cottrell believes is highly unlikely considering only 4 customers were involved and Cottrell has been in direct communications with each of those 4 customers, then Cottrell will reimburse the customer for the costs of the 4 reflectors as well as labor costs up to one-half hour per unit for installing them.

How Remedy Component Differs Once the 4 reflex reflectors are installed on the 1-Car Carriers in the field,

from Recalled Component: there will not be a difference.

Identify How/When Recall Condition Beginning with units manufactured on 8/10/2021, the 4 reflex reflectors was Corrected in Production: are being installed in production.

Recall Schedule:

Description of Recall Schedule: The one customer who received the citation and notified Cottrell on

8/6/21 has the vast majority of affected units in its fleet, 812 of the 878. Of the remaining units, 1 customer has 64 and the other 2 have 1 unit each. Cottrell is already in contact with some of the 4 customers, and due to our close working relationship with all of them, the other customers

will be officially notified on 8/11/2021.

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: AUG 11, 2021 - NR

* NR - Not Reported