

Part 573 Safety Recall Report

21V-642

Manufacturer Name : Newmar Corporation**Submission Date :** AUG 17, 2021**NHTSA Recall No. :** 21V-642**Manufacturer Recall No. :** DTNA #21V-556/FL-897**Manufacturer Information :****Population :**

Manufacturer Name : Newmar Corporation

Number of potentially involved : NR

Address : 355 North Delaware Street

Estimated percentage with defect : NR

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Vehicle Information :

Vehicle 1 : 2021-2022 Newmar Dutch Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Freightliner chassis, a fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire. Dutch Star=77

Production Dates : DEC 08, 2020 - AUG 06, 2021

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2021-2022 Newmar New Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Freightliner chassis, a fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire. New Aire=29

Production Dates : DEC 08, 2020 - AUG 06, 2021

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2021-2022 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Freightliner chassis, a fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire. Ventana=34

Production Dates : DEC 08, 2020 - AUG 06, 2021

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes built on a Freightliner chassis, a fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On certain motorhomes built on a Freightliner chassis, a fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire.

Description of the Cause : NR

Identification of Any Warning
that can Occur : NR

Involved Components :

Component Name 1 : 2 stage fuel filter

Component Description : NR

Component Part Number : Option numbers FF90942, FF90943, FF90944, FF91044

Supplier Identification :

Component Manufacturer

Name : Daimler Trucks North America LLC

Address : P.O. Box 3849

Portland Oregon 97208

Country : United States

Chronology :

On 08/10/2021, DTNA gave notice to Newmar of a potential defect on Freightliner chassis. Today, 08/17/2021, Newmar is giving notice of defect on Newmar motorhomes using Freightliner chassis.

Description of Remedy :

Description of Remedy Program : Cummins will be conducting this recall in its entirety. Cummins will contact all owners of these units that are affected by this recall. They will be directed to the appropriate service provider for repair. Cummins is currently developing a schedule for beginning the repairs. If you have questions or concerns about this recall, which correlates to Cummins recall 21E-063, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800-CUMMINS (1-800-286-6467) or visit our website at care.cummins.com.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 10/16/2021, customer/dealer letters will be sent out.

Planned Dealer Notification Date : OCT 16, 2021 - OCT 16, 2021

Planned Owner Notification Date : OCT 16, 2021 - OCT 16, 2021

* NR - Not Reported