

21PBJ - Hill Start Assist Valve Clearance - NHTSA ID: 21V-648, TC: 2021-521

Number

[Edit](#)[Clone](#)

21PBJ

Supplier

Peterbilt

Description

21PBJ - Hill Start Assist Valve Clearance - NHTSA ID: 21V-648, TC: 2021-521

Date

9/7/2021

What's New

Safety Recall – Interim Notification - Hill Start Assist (HSA) Valve Clearance – NHTSA ID: 21V-648, TC: 2021-521. Crossmember mounted Hill Start Assist valve may not have sufficient clearance to the rear axle, resulting in hose or fitting damage. Damage could cause the loss of rear brake signal, resulting in reduced braking capability and increasing the risk of a crash.

Introduction

Peterbilt has decided that a defect which relates to motor vehicle safety exists in certain model 367, 389, 567, and 579 vehicles manufactured from 12/01/2020 through 06/29/2021 and equipped with crossmember mounted Hill Start Assist valve.

Resolution

Safety Recall

This bulletin will be updated when the repair procedure and parts are available.