



IMPORTANT SAFETY RECALL

NHTSA ID: 21V669

Dear Boise Mobile Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Boise Mobile Equipment has been notified of a noncompliance issue involving the Code 3 79STTRBZ combination stop, tail, turn, reverse lamp used in the construction of your vehicle.

What is the Problem?

The subject lamps exceed the maximum permissible candela levels specified in Federal Motor Vehicle Safety Standard (FMVSS) No. 108 at certain test points.

The increased photometric intensity does not comply with the requirements of FMVSS 108 and may adversely affect the vision of following drivers, increasing the risk of a vehicle crash without warning.

What is the remedy?

The remedy involves installation a filter kit that will ensure that the lamps perform within the permissible photometric intensity ranges.

What should you do?

You can reach out to Code 3 / Ecco Group directly at 1-314-426-2700 to request two filter kits (Part number CZ0199) free of charge. Installation of the filter kit will ensure that the lamps perform within the permissible photometric intensity ranges. You may also contact the Boise Mobile service and warranty department at 1-208-858-8058 for assistance in obtaining the above-mentioned filter kits.

Who should you contact if you have further questions or concerns?

If you have any questions or concerns about this recall, please contact the Boise Mobile Equipment service and warranty department at 1-208-858-8058.

We apologize for any inconvenience but are sincerely concerned about your safety. Thank you.