

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER															
Safety Recall 47R3	Safety Recall	47R3	What vehicles are included in Safety Recall 47R3?	<table border="1"> <thead> <tr> <th>Country</th> <th>Beginning Model Year</th> <th>Ending Model Year</th> <th>Vehicle</th> <th>Vehicle Count</th> </tr> </thead> <tbody> <tr> <td>USA</td> <td>2021</td> <td>2021</td> <td>ARTEON</td> <td>99</td> </tr> <tr> <td>CAN</td> <td>2021</td> <td>2021</td> <td>ARTEON</td> <td>4</td> </tr> </tbody> </table>	Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count	USA	2021	2021	ARTEON	99	CAN	2021	2021	ARTEON	4
Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count															
USA	2021	2021	ARTEON	99															
CAN	2021	2021	ARTEON	4															
			What is the safety concern for Safety Recall 47R3?	The pressure input rod connection on the brake booster may not have been tightened correctly to factory specifications. If the pressure input rod detaches from the brake booster, the brake pedal will not work correctly to stop the vehicle, increasing the risk of a crash. The driver can still utilize the electric parking brake to stop the vehicle.															
			What is the repair for Safety Recall 47R3?	To correct this defect, your authorized Volkswagen dealer will inspect and, if necessary, tighten the affected screw to the proper value. This work will take about an hour to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.															
			When will the repair for Safety Recall 47R3 be available?	Parts are available now and repairs have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer .															