

# TRAIL KING Industries, Inc.

300 East Norway Avenue Mitchell, SD 57301-4777 Phone: (800) 843-3324 Fax: (605) 996-4727 2130 3<sup>rd</sup> Avenue NW West Fargo, ND 58078-1343 Phone: (800) 762-5557 Fax: (701) 282-3039 1200 Gehl Drive Yankton, SD 57078 Phone: (605) 665-8415 Fax: (605) 665-0810

TO: Valued TK80ACS/TK80AACS Trailer Customer NHTSA Recall Number: 21V-713

Trail King Recall Number: TK202104

DATE: October 6, 2021

## **IMPORTANT SAFETY RECALL**

Trail F	King ha	s d	etermined	that a	defect	which	relates to	motor	vehicle	safety	exists	in rear	axle sl	lide pan
	· ·			_						·			_	-

and suspension beams on certain TK80ACS and TK80AACS trailers. Only trailers with manufacture dates from August 2018 through October 2018 are affected.

## What Trailers are being recalled?

This notice applies to your vehicle with VIN:

This recall affects Trail King TK80ACS and TK80ACS 2019 model years that have manufacture dates August 2018 through October 2018.

#### What is the Problem?

During normal operation of the trailer, the rear sliding axle suspension beams can make contact with a frame reinforcement that is located directly above. Over time, the vehicle may experience cracking in the suspension beams in the location where the beams make contact with the frame reinforcements. If the cracks in the suspension beam continue to develop and are not addressed, the cracks could propagate and allow the suspension beam to come loose or fully detach from the frame bracket, increasing the potential for a crash.

## What should you do?

Obtain and confirm your trailer's serial number from the VIN plate located on the driver's side of the upper deck. You are receiving this letter because our records show you are the current owner of this vehicle.

A Trail King dealer will inspect the suspension beams and frame reinforcement. If there are signs of cracking, the trailer will need to be taken out of service until the repair can be completed. Please contact your nearest Trail King Industries dealer to have your trailer inspected and repaired. You also can contact Trail King Industries directly at 1-800-843-3324 and our Customer Service Department will help you locate a dealer near you. We will send the parts needed to the dealer to repair your trailer.

### What will we do?

Trail King Industries is conducting a safety recall campaign to address this issue. An authorized Trail King Industries Service Center will inspect and repair the suspension beams and frame reinforcement on your trailer. These repairs should take approximately 10 hours and will be performed at no charge to you.

If this repair has been performed prior to receipt of this notification, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information, contact Trail King at the phone number noted below.

If you no longer own the vehicle covered by this Safety Recall Notice, please provide the name and contact information for the new owner by contacting Trail King Industries at 1-800-843-3324 and ask for Customer Service or email to <a href="mailto:Customerservice@trailking.com">Customerservice@trailking.com</a>. This will enable us to advise the new owner of this recall.

Pursuant to Federal Law, any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If Trail King Industries fails or is unable to provide a remedy within a reasonable time, you may wish to contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or contact NHTSA at http://www.safercar.gov.

We regret any inconvenience this may cause you, but we are initiating this action in the interest of your personal safety and satisfaction with our products.

Sincerely, Customer Service

Trail King Industries 300 East Norway Mitchell, SD 57301 1-800-843-3324 (Toll Free)