

DRV Caliper Clip issue timeframe

8/9 – notified by Chad Olinger (warranty mgr CRV/DRV) of a possible issue with rotor bolts coming lose

8/12 – Chad, working with Dexter Axle, provided scope for rotor bolt issue

8/12 – set up meeting with Dexter, MorRyde, and Kodiak (owned by Dexter) for Aug 17.

8/17- Met with Dexter, MorRyde and Kodiak. Came to agreement to look over and do additional testing with DRV Unit. Will meet with Dexter to go over Torguing and testing. Met on 8/20 at DRV in Howe, Indiana to do additional testing.

8/20 – met with dexter service team to do additional test to try and pinpoint issue. Also fix and time study.

8/25 – email with dexter about needing additional information. Dexter is trying to pinpoint when they switched processes in production.

9/7 – email with dexter about needing additional information. Dexter finalizing scope, fix and information.

9/15 – received final information from Dexter axel about scope and fix

9/20 – sent info to safety committee