



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

October 13, 2021

Ms. Larissa Stoffels
Exec Mgr, Vehicle Safety
Daimler Trucks North America, LLC
4747 N. Channel Ave
Portland, OR 97217

NEF-107MR
21V-741

Subject: Solenoid Connector to CNG Fuel Tank May Corrode

Dear Ms. Stoffels:

This letter serves to acknowledge Daimler Trucks North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

THOMAS BUILT BUSES/MINOTOUR/2015-2018

Mfr's Report Date: September 23, 2021

NHTSA Campaign Number: 21V-741

Components:

ELECTRICAL SYSTEM:WIRING:RELAYS/SOLENOIDS
FUEL SYSTEM, OTHER:STORAGE:TANK ASSEMBLY

Potential Number of Units Affected: 87

Problem Description:

Daimler Trucks North America, LLC. (DTNA) is recalling certain 2015-2018 Thomas Built Minotour school buses. The under-body shut-off solenoid connector that connects to the CNG fuel tank may corrode, which could result in an electrical short.

Consequence:

A short at the connector may cause a flame or overheating, increasing the risk of a fire.

Remedy:

Dealers will replace the CNG fuel shut-off solenoid, free of charge. Owner notification letters are expected to be mailed on November 14, 2021. Owners may contact DTNA's customer service at 1-800-547-0712. DTNA's number for this recall is FL-903.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)). All filings should state an increased risk of either a crash, injury or fire.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Daimler Trucks North America, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement