

GM CUSTOMER CARE AND AFTERSALES
DCS5972
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 22, 2021

Subject: N212349181 01 – Safety Recall – Recall Reinstated
Underhood Fire

Models: 2021-2022 Chevrolet Silverado 2500/3500
2021-2022 GMC Sierra 2500/3500

To: All General Motors Dealers

On October 21, 2021, we temporarily suspended Safety Recall N212349181 via GM GlobalConnect Message GCUS-3-2347. We are pleased to announce that this has been reinstated and dealers can resume repairing vehicles.

This bulletin has also been revised to add a warning statement to the service procedure and additional instructions before replacing the EBCM/BPMV. Please discard all copies of bulletin N212349181.

Involved vehicle status in IVH will be changed back to an Open status on October 22, 2021. We apologize for any inconvenience this situation may have caused.

GM CUSTOMER CARE AND AFTERSALES