



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121 1904



771487949139

A/1/000001/1

November 2021



JOHN A. SAMPLE
123 SAMPLE ST
SAMPLE CITY, MI 12345-6789

*** * * IMPORTANT SAFETY RECALL * * ***

Compliance Recall Notice 21C23 / NHTSA Recall 21V770000

2021 Bronco

Your Vehicle Identification Number (VIN): XXXXXXXXXXXXXXXXXXXX

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that your vehicle, with the VIN shown above, fails to conform to Federal Motor Vehicle Safety Standard (FMVSS) 208 Occupant Protection.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue? On your vehicle, the front passenger airbag may have been incorrectly folded by the supplier.

What is the risk? Incorrect folding may cause improper deployment of the airbag, increasing the risk of occupant injury during a crash.

What will Ford and your dealer do? Ford Motor Company is working closely with its suppliers to produce parts for this repair. When parts become available, Ford Motor Company will notify you via mail to schedule a service appointment with your dealer to have the airbag replaced free of charge (parts and labor). Parts are anticipated to be available late 4th quarter of 2021.

What should you do? When parts are available, Ford Motor Company will send a letter to inform you that parts are available and to contact your dealer to schedule a repair. Ford has not issued instructions to stop driving your vehicle under this compliance recall. When parts are available, you should contact your dealer for an appointment to have your vehicle remedied as soon as practicable. You can continue to safely drive your vehicle.

If you do not already have a servicing dealer, you can access owner.ford.com for dealer addresses, maps, and driving instructions.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

COVID-19 (CORONAVIRUS) Ford dealerships have implemented enhanced protocols to ensure both your safety and the safety of dealership employees. This includes specific procedures for cleaning and disinfecting customer vehicles before and after each vehicle is serviced. In most places, vehicle service has been deemed a critical service. Please contact your local dealer to confirm current service hours. For more information on how Ford and your local dealer are working hard to keep you on the road during these challenging times, please visit owner.ford.com.

Thank you for your attention to this important matter.

Ford Customer Service Division



Ford Motor Company
 División de Servicio al Cliente de Ford
 P. O. Box 1904
 Dearborn, Michigan 48121



771487949139

A/2/000001/1

Noviembre de 2021



JOHN A. SAMPLE
 123 SAMPLE ST
 SAMPLE CITY, MI 12345-6789

*** * * CAMPAÑA DE SEGURIDAD IMPORTANTE * * ***

Aviso de campaña de cumplimiento 21C23 / Campaña 21V770000 de la NHTSA

2021 Bronco

Número de identificación del vehículo (VIN): [REDACTED]

Este aviso se le envía de acuerdo con la Ley Nacional de Seguridad y Tránsito de Vehículos de los EE. UU.

Ford Motor Company ha determinado que su vehículo, con el VIN que aparece más arriba, no cumple con la norma federal de seguridad para vehículos de motor (FMVSS) 208 Protección del ocupante.

Lamentamos esta situación y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

- ¿Cuál es el problema?** La bolsa de aire del pasajero delantero de su vehículo podría haber sido plegada de forma incorrecta por el proveedor.
- ¿Qué riesgo existe?** Un plegado incorrecto podría generar un despliegue inadecuado de la bolsa de aire, lo cual aumenta el riesgo de que el ocupante sufra lesiones durante un choque.
- ¿Qué medidas adoptarán Ford y su distribuidor?** Ford Motor Company colabora estrechamente con sus proveedores para fabricar las piezas para esta reparación. Cuando estas estén disponibles, Ford Motor Company le notificará mediante correo para programar una cita de servicio con su distribuidor a fin de reemplazar la bolsa de aire, sin costo alguno (piezas y mano de obra). Se prevé que las piezas estarán disponibles a fines del 4^{to} trimestre de 2021.
- ¿Qué debe hacer?** Cuando las piezas estén disponibles, Ford Motor Company le enviará una carta para informarle la disponibilidad de estas y solicitarle que se comunique con su distribuidor a fin de programar la reparación.
 Para esta campaña de conformidad, Ford no ha emitido instrucciones de dejar de manejar el vehículo. Cuando las piezas se encuentren disponibles, deberá ponerse en contacto con su distribuidor a fin de programar una cita para solucionar este problema lo más pronto posible. Puede continuar manejando su vehículo con seguridad.
 Si aún no tiene un distribuidor para realizar el servicio, puede acceder a owner.ford.com para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.
Tenga presente que: La ley federal exige que los arrendadores de vehículos que reciban este aviso de campaña envíen una copia del mismo al arrendatario en un plazo de diez días.

COVID-19 (CORONAVIRUS)

Los distribuidores Ford han implementado protocolos mejorados con el fin de asegurar tanto su seguridad como la de los empleados de los diferentes distribuidores. Esto incluye procedimientos específicos de limpieza y desinfección antes y después de realizar servicio en cada uno de los vehículos de nuestros clientes. En la mayoría de los lugares, la atención de vehículos se ha considerado un servicio esencial. Póngase en contacto con su distribuidor local para confirmar las horas de servicio actuales. Para obtener más información sobre cómo Ford y su distribuidor local están trabajando arduamente para mantenerlo en las calles durante estos tiempos difíciles, visite owner.ford.com.

Gracias por su atención en este asunto sumamente importante.

Ford, División de Servicio al Cliente