OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-772

Manufacturer Name: Corp. Micro Bird, Inc.

Submission Date: OCT 01, 2021 **NHTSA Recall No.:** 21V-772 **Manufacturer Recall No.:** 21-088-AUC



Manufacturer Information:

Manufacturer Name: Corp. Micro Bird, Inc.

Address: 3000, Rue Girardin

Drumondville, Quebec 00 J2E 0A1

Company phone: 819-477-2012

Population:

Number of potentially involved : 1 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2022-2022 Micro Bird G5

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Alignment ring installed at the wrong angle

Production Dates: JUN 01, 2021 - JUN 30, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: During wheel alignment of these buses at our facilities, the alignment ring was

installed at a wrong angle. In consequence, the alignment ring may pop out of

place, and the wheels may become misaligned.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Misaligned wheels may result in uneven tire wear, stress on suspension and

can cause steering problems. All these consequences may increase the risks of

an accident

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

tilat call occur.

Involved Components:

Component Name 1: NR Component Description: NR Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

During routine inspection of a vehicle, it was observed that an alignment ring was missing. Investigation of other vehicles aligned during the same period revealed that the ring had been installed at a wrong angle. The period during which alignments presented the same default has been determined and all vehicles still at our facilities have been re-aligned. It was decided to recall the vehicles aligned during the identified period that have already been delivered.

No claim was received concerning this default. No accident, injury or death linked to this default has been reported.

Description of Remedy:

Description of Remedy Program: Micro Bird will reimburse labor to have the wheels of the recalled vehicles

re-aligned at no charge for the owners

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Micro Bird will notify dealers by email and owners by mail. We plan on

sending the emails to dealers from October 4 and October 8. 2021, and

shipping the owners' notification between October 6 and October 22.

Planned Dealer Notification Date: OCT 04, 2021 - OCT 08, 2021

Part 573 Safety Recall	Report
------------------------	--------

21V-772

Page 3

Planned Owner Notification Date: OCT 06, 2021 - OCT 22, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573