OMB Control No.: 2127-0004

Recall Quarterly Report

21V-776

Manufacturer Name: Shyft Group

NHTSA Recall No. / MFR Recall No.: 21V-776 /21-22

Recall Subject: Rear Suspension Fasteners Not Tightened Properly

Owner Notification Beginning Date: NOV 16, 2021

Owner Notification End Date: NOV 16, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 12, 2022	2022-2	660	312	0	27
2	APR 19, 2022	2022-1	660	239	0	25
1	JAN 30, 2022	2021-4	660	132	0	2

This Document Last Updated: JUL 12, 2022

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.