# Part 573 Safety Recall Report

Manufacturer Name : Cruiser RV Submission Date : OCT 14, 2021 NHTSA Recall No. : 21V-802 Manufacturer Recall No. : NR

### Manufacturer Information :

Manufacturer Name : Cruiser RV Address : 7805 North State Road 9 PO Box 130 Howe IN 46746 Company phone : 866-277-5630

## Vehicle Information :

Vehicle 1:2021-2022 Cruiser HitchVehicle Type :TRAILERSBody Style :OTHERPower Train :NRDescriptive Information :The Federal certification label does not have the correct (GAWR) axle rating.

 Production Dates :
 MAR 03, 2021 - OCT 08, 2021

 VIN Range 1 : Begin :
 5RXRB2110M1467193
 End :
 5RXRB2112N1489892
 ✓ Not sequential

**Population**:

## **Description of Noncompliance :**

Description of the<br/>Noncompliance :Travel Trailers do not conform to 49 CFR Part 567 – Certification and Federal<br/>Motor Vehicle Safety Standard

FMVSS 1 :	120 - Wheels and rims- other than passenger cars
FMVSS 2 :	NR
Description of the Safety Risk :	The owner would not know the actual axle weight rating of the unit and it could be overloaded due to incorrect axle listing.

# Description of the Cause : The information for the GAWR (axle rating) was entered incorrectly into the model table for this model unit.

Identification of Any Warning N/A that can Occur :

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 264 Estimated percentage with defect : 100 %



21V-802

# Part 573 Safety Recall Report

#### **Involved Components :**

Component Name 1: NR

Component Description : NR

Component Part Number: NR

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : NR

Address : NR NR

Country: NR

#### **Chronology** :

10/11/2021 - Engineering caught discrepancy with GAWR; 10/12/2021 ran scope of the known issue: 10/13/2021 Safety committee voted.

#### **Description of Remedy :**

Description of Remedy Program :	The manufacture will send out replacement certification labels. This will be corrected at no expense to the owner. All reimbursements will be covered by Cruiser's general reimbursement plan.
How Remedy Component Differs from Recalled Component :	The GAWR (axle ratings) will be corrected on the new certification labels.
Identify How/When Recall Condition was Corrected in Production :	It corrected the GAWR in the system so the VIN tags will print properly.

#### **Recall Schedule :**

Description of Recall Schedule : Mailing will begin once approval is received

The information contained in this report was submitted pursuant to 49 CFR §573

Planned Dealer Notification Date : DEC 13, 2021 - DEC 13, 2021 Planned Owner Notification Date : DEC 13, 2021 - DEC 13, 2021

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573