

Part 573 Safety Recall Report

21V-803

Manufacturer Name : Provan Industries, LLC

Submission Date : FEB 11, 2022

NHTSA Recall No. : 21V-803

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Provan Industries, LLC

Address : 4837 Edmund Hwy.
West Columbia SC 29170

Company phone : 803-955-3001

Population :

Number of potentially involved : 13

Estimated percentage with defect : 50 %

Vehicle Information :

Vehicle 1 : 2019-2020 Tiger Adventure Vehicle Bengal TX

Vehicle Type : LOW VOLUME VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Our records show that this recall potentially affects 13 Bengal campers produced between 09/19 and 01/21 with OPIM numbers 1310B- 1322B.

Production Dates : SEP 01, 2019 - JAN 01, 2021

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Lippert Components has determined that some window vents may experience an issue with the window adhesive bonding.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Inner and outer glass panes may become separated. A pane falling off may cause a crash or injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : Window vent

Component Description : Galley window front vent

Component Part Number : 6402-40-P SVD 54.7 X 081 G20 TP BK 4.000 RADII

Component Name 2 : Window vent

Component Description : Galley window rear vent

Component Part Number : 6402-40-R SVD 54.7 X 081 BK TP G20 4.000 RADII*

Component Name 3 : Window vent

Component Description : Couch window front vent

Component Part Number : 6402-40-R SVD 58.7 X 081 G20 TP BK 4.000 RADII

Component Name 4 : Window vent

Component Description : Couch window rear vent

Component Part Number : 6402-40-P SVD 58.7 X 081 BK TP G20 4.000 RADII

Supplier Identification :

Component Manufacturer

Name : Lippert Components

Address : 88704 Expedite Way.
Chicago Illinois 60695

Country : United States

Chronology :

Provan was notified of the recall by Lippert Components on 7-2-21. Provan RV Industries contacted Lippert Components immediately to order test gauges, the recall description, and replacement part numbers. The recall was filed On 10-14-21. At the time of filing, there were no claims or injuries reported.

Description of Remedy :

Description of Remedy Program : Provan RV Industries will send an inspection gauge along with recall instructions to the potentially affected Bengal owners. Lippert Components will pay 0.4 hours labor to inspect the involved windows and/or 0.5 hours labor to replace any needed vent. Provan RV Industries will pay the repair shop directly and be reimbursed by Lippert Components later. Replacement parts are readily available.

How Remedy Component Differs from Recalled Component : Better adhesive

Identify How/When Recall Condition was Corrected in Production : No correction necessary on the part of Provan RV Industries.

Recall Schedule :

Description of Recall Schedule : No dealers or distributors.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported