

U.S. Department of Transportation

National Highway Traffic Safety Administration

October 27, 2021

Mr. Mike Becker Director of Corporate Compliance Forest River, Inc. 2324 Century Drive Goshen, IN 46528 NEF-107KL 21V-829

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Incorrect Wiring/Missing Over-Current Protection

Dear Mr. Becker:

This letter serves to acknowledge Forest River, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FOREST RIVER/XLR TOYHAULER/2022

Mfr's Report Date: October 22, 2021

NHTSA Campaign Number: 21V-829

Components:

ELECTRICAL SYSTEM:12V/24V/48V BATTERY
ELECTRICAL SYSTEM:WIRING
EQUIPMENT:RECREATIONAL VEHICLE/TRAILER:120/240 VAC ELECTRICAL SYSTEM:INVERTER

Potential Number of Units Affected: 3

Problem Description:

Forest River, Inc. (Forest River) is recalling certain 2022 XLR Toy Hauler Recreational Vehicles. The vehicles were incorrectly wired, and they are missing 250AMP over-current protection, which could result in melted wires and an electrical short.

Consequence:

An electrical short increases the risk of a fire.

Remedy:

The remedy is still under development. Owner notification letters are expected to be mailed December 1, 2021. Owners may contact Forest River Customer Service at 1-574-642-0432. Forest River's number for this recall is 79-1429.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Forest River, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

