

**From:** [Broadcast Messaging System](#)  
**To:** [DL-BMS Message Monitors](#)  
**Subject:** BMW Recall 21V-831: Rear License Plate Illumination  
**Date:** Monday, October 25, 2021 2:23:03 PM

Publish Date: October 25, 2021  
From: Technical Service  
Expiration Date: November 15, 2021

DCSnet Message  
**Urgent**



Subject: **BMW Recall 21V-831: Rear License Plate Illumination**

BMW AG is conducting a Voluntary Non-Compliance Recall (effective October 25, 2021) on certain Model Year 2022 BMW X4 SAC models that were produced between July 27, 2021 and October 19, 2021.




The illumination of the rear license plate may not meet a Federal requirement. The rear license plate bracket will be modified.

See attached for more details.

Remedy is available. Please disregard remedy status in the system ? it will change to remedy available later this week.

Sincerely,  
Technical Service

Attachments:

 [B512121\\_Recall\\_Notice\[1635185981111\].pdf](#)  
 [B512121\[1635185981111\].pdf](#)  
 [B512121\\_2021-BMW-MY2022-G02-RearLicensePlateIllumination-FAQ-\(22Oct2021\)\[1635185981111\].pdf](#) [B512121\\_Recall\\_Notice\[1635185981111\].pdf](#)  
[B512121\[1635185981111\].pdf](#)  
[B512121\\_2021-BMW-MY2022-G02-RearLicensePlateIllumination-FAQ-\(22Oct2021\)\[1635185981111\].pdf](#)

Recipients: BMW Passenger Cars, All Offering, All Region, All Areas, All Departments, All Personnel  
BMW SAV (Light Trucks), All Offering, All Region, All Areas, All Departments, All Personnel  
BMW Passenger Cars, CC-All