

U.S. Department of Transportation

National Highway Traffic Safety Administration

November 10, 2021

Tiffani Torgeson Daimler Trucks North America, LLC 4747 N Channel Ave Portland, OR 97217 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107MR 21V-850

**Subject:** Alternator Power Cable Connection May be Loose

## Dear Tiffani Torgeson:

This letter serves to acknowledge Daimler Trucks North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

# Makes/Models/Model Years:

THOMAS BUILT BUSES/SAF-T-LINER EFX/2020-2022 THOMAS BUILT BUSES/SAF-T-LINER HDX/2020-2022

Mfr's Report Date: November 2, 2021

NHTSA Campaign Number: 21V-850

#### **Components:**

ELECTRICAL SYSTEM:ALTERNATOR/GENERATOR/REGULATOR

**Potential Number of Units Affected:** 1.434

### **Problem Description:**

Daimler Trucks North America, LLC (DTNA) is recalling certain 2020-2022 Thomas Built EFX and HDX school buses. The nut for the power cable stud on the alternator may not have been tightened properly, which can cause a loose cable connection.

### **Consequence:**

A loose power cable connection may cause electrical arcing, which can increase the risk of a fire.

## Remedy:

Dealers will inspect the alternator power cable connection and tighten it if necessary, free of charge. Owner notification letters are expected to be mailed December 31, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL904.

#### **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



# Please ensure the following requirements are met:

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Daimler Trucks North America, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

