

**Recall Quarterly Report****21V-852**

**Manufacturer Name :** Volkswagen Group of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 21V-852 /48Q7  
**Recall Subject :** Missing Drive Bushing May Cause Steering Loss  
**Owner Notification Beginning Date :** NOV 05, 2021  
**Owner Notification End Date:**



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 27, 2022	2021-4	1	1	0	0

This Document Last Updated : JAN 27, 2022

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.