VOLKSWAGEN DEALER COMMUNICATION – USA ONLY

Repair Available - Safety Recall 48Q7 / Steering Gear

This notice is for:	 ✓ Dealer Principal ✓ General Manager ✓ Sales Managers 	 ✓ Service Mana ✓ Parts Manag ✓ Service Cons 	er 🗸 Technici	y Administrator ans
Date:	November 04, 2021			
Issue:	The one (1) vehicle included in this recall may have received an incorrectly assembled or missing steering assembly worm gear drive bushing. If the bushing is missing or incorrectly assembled, it will result in loud noises while using the steering in low speed situations like parking. If ignored, this may lead to a failure of the steering support with increased steering forces and a blockage cannot completely be ruled out. This may increase the risk of a crash.			
Repair:	 Volkswagen Customer CARE will contact the one affected customer via telephone and will assist in arranging this recall repair with an authorized Volkswagen dealer. 			
	• The steering gear will be replaced on the affected vehicle.			
	 Parts required to repair this vehicle will be coordinated directly with the repairing dealer. 			
	Destinuing	E se al lise se		Mahiala
Affected Vehicles	Country Beginning Model Yea		Vehicle	Vehicle Count
Affected Vehicles			Vehicle ID.4	
Affected Vehicles	Country Model Yea	r Model Year 2022 on; some vehicles may for ir to verify that a VIN qua	ID.4 have already been repaired. Cl	Count 1 heck Campaigns/Actions
Affected Vehicles Notes:	Country Model Yea USA 2022 *Counts reflect overall population screen in Elsa on the day of repair	r Model Year 2022 on; some vehicles may f ir to verify that a VIN qua source. overage cannot b red under the Alter ty Policy and Proce	ID.4 have already been repaired. Cl alifies for repair under this action e claimed under this mate Transportation Pro-	Count 1 heck Campaigns/Actions on. Elsa is the <u>only</u> valid action. However, ogram. Please refer
	Country Model Yea USA 2022 *Counts reflect overall populati screen in Elsa on the day of repaction campaign inquiry & verification U.S.A.: Loaner/rental cover to the Volkswagen Warrar	r Model Year 2022 on; some vehicles may f ir to verify that a VIN qua source. overage cannot b red under the Alten ty Policy and Proce	ID.4 have already been repaired. Cl alifies for repair under this action e claimed under this mate Transportation Pro- edures Manual for loane	Count 1 heck Campaigns/Actions on. Elsa is the <u>only</u> valid action. However, ogram. Please refer r claims information
	Country Model Yea USA 2022 *Counts reflect overall populati screen in Elsa on the day of repace campaign inquiry & verification U.S.A.: Loaner/rental country box USA	Model Year 2022 on; some vehicles may I ir to verify that a VIN quasource. overage cannot b red under the Alter ty Policy and Process. EHICLES AFFECTED entory: it is a violation used item of motor v e or lease until the d of delivery for sale or ehicle Safety Standar	ID.4 have already been repaired. Ch alifies for repair under this action e claimed under this renate Transportation Pro- edures Manual for loane BY SAFETY & COMPLIAN n of federal law for a dea ehicle equipment (including effect or noncompliance is lease, any vehicle that fail d or that contains a defen-	Count 1 heck Campaigns/Actions on. Elsa is the only valid action. However, ogram. Please refer r claims information ICE RECALLS ler to deliver a new ng a tire) covered by s remedied. By law, s to comply with an ct relating to motor e-owned vehicles in

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.