

Part 573 Safety Recall Report

21V-866

Manufacturer Name : Keystone RV Company

Submission Date : NOV 08, 2021

NHTSA Recall No. : 21V-866

Manufacturer Recall No. : 21-417



Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 133

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Keystone Arcadia 3660RL

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Model – 3660RL

Production Dates : AUG 23, 2021 - OCT 28, 2021

VIN Range 1 : Begin : 4YDFARR20NL550074 **End :** 4YDFARR20NL550401 Not sequential

Description of Defect :

Description of the Defect : It has been decided that the vehicles in the recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the tire size is ST235/80R16G and the pressure as 110 PSI. The correct tire size is ST235/80R16E and the pressure is 80 PSI.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An incorrect label may lead to unintentionally overinflating the tires, increasing the risk of a crash.

Description of the Cause : The incorrect tire pressure information was printed on the label

Identification of Any Warning that can Occur : PSI on the Federal Identification Tag does not match information for the rim and tire.

Involved Components :

Component Name 1 : Fed Tag

Component Description : Label - Tread Gen Fed Cert Combo Laser - 9/05 - FD316

Component Part Number : 192406

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

11/1/2021 – Report was made by engineering that the FED ID tag info was incorrect for the tire PSI.

11/3/2021 – Range and Scope completed.

Description of Remedy :

Description of Remedy Program : The remedy is to replace the Federal Identification Tag. Manufacturer Reimbursement Plan on file as of 10/07/2020. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

How Remedy Component Differs from Recalled Component : The repair will conform to requirements of Part 567, "Certification."

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : DEC 29, 2021 - DEC 29, 2021

Planned Owner Notification Date : DEC 29, 2021 - DEC 29, 2021

* NR - Not Reported