



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 19, 2021

Mr. John McDonald
Maserati North America, Inc.
1 Chrysler Dr.
Auburn Hills, MI 48326

NEF-107JK
21V-872

Subject: Fuel Line Sensor Housing May Leak

Dear Mr. McDonald:

This letter serves to acknowledge Maserati North America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MASERATI/GHIBLI/2021
MASERATI/LEVANTE/2021-2022
MASERATI/MC20/2022
MASERATI/QUATTROPORTE/2021

Mfr's Report Date: November 10, 2021

NHTSA Campaign Number: 21V-872

Components:

FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS
FUEL SYSTEM, GASOLINE:DELIVERY:PRESSURE SENSOR

Potential Number of Units Affected: 409

Problem Description:

Maserati North America, Inc. (Maserati) is recalling certain 2021 Quattroporte, Ghibli, 2021-2022 Levante, and 2022 MC20 vehicles. The fuel line sensor housing may crack and leak fuel.

Consequence:

A fuel leak may cause an engine stall, increasing the risk of a crash. A fuel leak also increases the risk of fire in the presence of an ignition source.

Remedy:

Dealers will replace the fuel line sensor housing, free of charge. Owner notification letters are expected to be mailed December 27, 2021. Owners may contact Maserati customer service at 1-877-696-2737. Maserati's number for this recall is 442.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Maserati North America, Inc.'s contact for this recall will be Jennifer Kruger who may be reached by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement