

Part 573 Safety Recall Report

21V-887

Manufacturer Name : M H EBY**Submission Date :** DEC 27, 2021**NHTSA Recall No. :** 21V-887**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : M H EBY

Address : 1194 Main St

Blue Ball PA 17506

Company phone : 354-4971

Population :

Number of potentially involved : 836

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2022 EBY Generation

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : A change in manufacturing facilities took place at which time production failed to add the conspicuity to the top rear corner of the commodity trailers. This happened in a single manufacturing facility.

Population of 836 trailers were produce from 7/22/2019 until 11/12/2021, the affected population is the EBY Generation, only model years 2020 thru and including 2022 year to date.

Production Dates : JUL 22, 2019 - NOV 12, 2021VIN Range 1 : Begin : 4A2MH402XN3006026 End : 4A2MH4221N3007501 Not sequentialVIN Range 2 : Begin : 4A2MH4020L3005738 End : 4A2MH4021L3006008 Not sequentialVIN Range 3 : Begin : 4A2MH5039M3005821 End : 4A2MH402XM3006641 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : White conspicuity tape was not install on the top rear corners of the commodity trailers as required by FMVSS 393.11 (B)

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Could cause the physical acuity of a driver not recognize the rear of the trailer

Description of the Cause : The conspicuity tape was not installed during the manufacturing process as needed in accordance with FMVSS 393.11 (B)

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : White Conspicuity Tape

Component Description : 300MM length white conspicuity tape stamped with DOT 2

Component Part Number : LD42060

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

No complaints have been received from our customers. The missing white conspicuity tape was noticed in a sales brochure on 11/12/2021.

Description of Remedy :

Description of Remedy Program : We will ship to the customer four(4) pieces of 300MM in length white conspicuity tape, stamped with the DOT2, 4 alcohol swabs to prep the area, detailed instructions and a drawing where to have the conspicuity tape installed as well as a stamped self addressed postcard for the customer to confirm the installation. The notice will be sent certified mail

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : The installation of the tape was added to the manufacturing process as a line item. Upon completion of the trailer build a quality inspection is performed. This also has the line item added to insure the tape is installed.

Recall Schedule :

Description of Recall Schedule : All trailer affected were sold factory direct, none were sold through our dealer network. The data base of customers was pulled from our system,

The information includes name, physical address, city, state and zip code of the purchaser

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : DEC 15, 2021 - JAN 14, 2022

* NR - Not Reported