OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-896

Manufacturer Name: Daimler Trucks North America, LLC

Submission Date: NOV 22, 2021 NHTSA Recall No.: 21V-896 Manufacturer Recall No.: FL-908



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America, LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved: 413 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2011-2022 Freightliner SD

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: All vehicles listed in DTNA's database as having been built with the particular tire and

rim combinations.

Production Dates: JUL 21, 2011 - JAN 30, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2013-2022 Western Star 4700

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: All vehicles listed in DTNA's database as having been built with the particular tire and

rim combinations.

Production Dates: MAR 20, 2012 - JUN 09, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 3: 2016-2016 Freightliner Coronado

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: All vehicles listed in DTNA's database as having been built with the particular tire and

rim combinations.

Production Dates: AUG 03, 2015 - AUG 03, 2015

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 4:	2011-2022 Wes	tern Star 4900		
Vehicle Type :	7011 7077 1105	1000		
Body Style :				
Power Train:	NR			
Descriptive Information :	All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.			
Production Dates :	OCT 15, 2010 - JUL 14, 2021			
VIN Range 1:		NR	End: NR	☐ Not sequential
Vehicle 5:	2013-2013 Wes	tern Star 6900		
Vehicle Type :				
Body Style :				
Power Train :	NR			
Descriptive Information :	All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.			
Production Dates :	APR 20, 2012 - JUN 04, 2012			
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential
Vehicle 6: 2022-2022 Western Star 49X				
Vehicle Type :				
Body Style :				
Power Train :	NR			
Descriptive Information :	All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.			
Production Dates :	JUN 04, 2021 - SEP 02, 2021			
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential

Description of Noncompliance:

Description of the On the affected vehicles, the tire/rim combination was not on the approved list

Noncompliance: from the Tire and Rim Association or listed as approved by the tire

manufacturer at the time of sale, as required by FMVSS 120, after the tire/rim

combination was removed from the list.

FMVSS 1: 120 - Wheels and rims- other than passenger cars

FMVSS 2: NR

Description of the Safety Risk: Failure to meet the standard without getting tire manufacturer approval

increases the risk of an accident.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: Certain tire/rim combinations

Component Description: NR Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

On Sep 29, 2021 DTNA was made aware of a potential tire rim mismatch. DTNA promptly began an investigation, in which it was found that the Tire and Rim Association had made changes to the approved wheel list for certain tires, removing certain combinations. Upon determining the existence of a noncompliance, on Nov 10, 2021 DTNA decided to conduct a non-compliance recall. On Nov 22, 2021, with further information, DTNA amended the affected population.

Description of Remedy:

Description of Remedy Program: The remedy has not been finalized. Repairs will be made by Daimler

Trucks North America authorized service facilities.

Details of the reimbursement plan will be included in the owner's

notification letter.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Part 573 Safety Recall Report

21V-896

Page 4

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : JAN 15, 2022 - JAN 15, 2022 Planned Owner Notification Date : JAN 15, 2022 - JAN 15, 2022

* NR - Not Reported