

Part 573 Safety Recall Report

21V-896

Manufacturer Name : Daimler Trucks North America, LLC

Submission Date : JAN 21, 2022

NHTSA Recall No. : 21V-896

Manufacturer Recall No. : FL-908



Manufacturer Information :

Manufacturer Name : Daimler Trucks North America, LLC

Address : 4747 N. Channel Avenue
Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 413

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2011-2022 Freightliner SD

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.

Production Dates : JUL 21, 2011 - JAN 30, 2021

VIN Range 1 : Begin : NR **End :** NR ☐ Not sequential

Vehicle 2 : 2013-2022 Western Star 4700

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.

Production Dates : MAR 20, 2012 - JUN 09, 2021

VIN Range 1 : Begin : NR **End :** NR ☐ Not sequential

Vehicle 3 : 2016-2016 Freightliner Coronado

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.

Production Dates : AUG 03, 2015 - AUG 03, 2015

VIN Range 1 : Begin : NR **End :** NR ☐ Not sequential

Vehicle 4 : 2013-2013 Western Star 6900

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.

Production Dates : APR 20, 2012 - JUN 04, 2012

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 5 : 2022-2022 Western Star 49X

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.

Production Dates : JUN 04, 2021 - SEP 02, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 6 : 2011-2022 Western Star 4900

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles listed in DTNA's database as having been built with the particular tire and rim combinations.

Production Dates : OCT 15, 2010 - JUL 14, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Noncompliance :

Description of the Noncompliance : On the affected vehicles, the tire/rim combination was not on the approved list from the Tire and Rim Association or listed as approved by the tire manufacturer at the time of sale, as required by FMVSS 120, after the tire/rim combination was removed from the list.

FMVSS 1 : 120 - Wheels and rims- other than passenger cars

FMVSS 2 : NR

Description of the Safety Risk : Failure to meet the standard without getting tire manufacturer approval increases the risk of an accident.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Michelin 445/65R22.5 Tires

Component Description : 445/65R22.5 Tires on 12.25" Rims

Component Part Number : 445/65R22.5 Tires

Component Name 2 : Continental 445/65R22.5 Tires

Component Description : 445/65R22.5 Tires on 12.25" Rims

Component Part Number : 445/65R22.5 Tires

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On Sep 29, 2021 DTNA was made aware of a potential tire rim mismatch. DTNA promptly began an investigation, in which it was found that the Tire and Rim Association had made changes to the approved wheel list for certain tires, removing certain combinations. Upon determining the existence of a noncompliance, on Nov 10, 2021 DTNA decided to conduct a non-compliance recall. On Nov 22, 2021, with further information, DTNA amended the affected population.

Description of Remedy :

Description of Remedy Program : Vehicles with suspect tire/rim combinations will be replaced with tires approved for this tire/rim combination. Replacements will be made by Daimler Truck North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : JAN 15, 2022 - JAN 15, 2022

Planned Owner Notification Date : JAN 15, 2022 - JAN 15, 2022

* NR - Not Reported